

















## CARFAX® Vehicle History Report™

An independent company established in 1986

US \$39.99

<p><b>Vehicle Information:</b>  <b>1987 MERCEDES-BENZ 560SL</b>                  VIN: WDBBA48DXHA070677                  CONVERTIBLE                  5.6L V8 FI                  GASOLINE                  REAR WHEEL DRIVE  <a href="#">Standard Equipment</a>   <a href="#">Safety Options</a></p> <p><b>CARFAX Report Provided By:</b>                  Mohr Imports                  1187 Del Monte Ave                  Monterey, CA 93940                  831-373-3131                  www.mohrimports.com</p>	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center; width: 30px;"></td> <td>No accidents reported to CARFAX</td> </tr> <tr> <td style="text-align: center;"></td> <td>No other damage reported to CARFAX</td> </tr> <tr> <td style="text-align: center;"></td> <td><b>21</b> Service history records</td> </tr> <tr> <td style="text-align: center;"></td> <td><b>38</b> Detailed records available</td> </tr> <tr> <td style="text-align: center;"></td> <td><b>74,257</b> Last reported odometer reading</td> </tr> </table>		No accidents reported to CARFAX		No other damage reported to CARFAX		<b>21</b> Service history records		<b>38</b> Detailed records available		<b>74,257</b> Last reported odometer reading	
	No accidents reported to CARFAX											
	No other damage reported to CARFAX											
	<b>21</b> Service history records											
	<b>38</b> Detailed records available											
	<b>74,257</b> Last reported odometer reading											

This CARFAX Vehicle History Report is based only on [information](#) supplied to CARFAX and available as of 7/7/17 at 8:47:18 PM (EDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.




### Title History

CARFAX guarantees the information in this section


Summary

<p><a href="#">Salvage</a>   <a href="#">Junk</a>   <a href="#">Rebuilt</a>   <a href="#">Fire</a>   <a href="#">Flood</a>   <a href="#">Hail</a>   <a href="#">Lemon</a></p>	<p style="color: green; font-weight: bold;">Guaranteed</p> <p>No Problem</p>
<p><a href="#">Not Actual Mileage</a>   <a href="#">Exceeds Mechanical Limits</a></p>	<p style="color: green; font-weight: bold;">Guaranteed</p> <p>No Problem</p>



GUARANTEED







- None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. [Register](#) | [View Terms](#)



### Additional History

Not all accidents / issues are reported to CARFAX

Summary

<p><b>Total Loss</b> No total loss reported to CARFAX.</p>	<p> No Issues Reported</p>
<p><b>Structural Damage</b> No structural damage reported to CARFAX.</p>	<p> No Issues Reported</p>
<p><b>Airbag Deployment</b> No airbag deployment reported to CARFAX.</p>	<p> No Issues Reported</p>
<p><b>Odometer Check</b> No indication of an odometer rollback.</p>	<p> No Issues Indicated</p>
<p><b>Accident / Damage</b> No accidents or damage reported to CARFAX.</p>	<p> No Issues Reported</p>
<p><b>Manufacturer Recall</b> Check with an authorized Mercedes-Benz dealer for any open recalls.</p>	<p> No Recalls Reported</p>



Date:	Mileage:	Source:	Comments:
11/25/1991	10,527	California Inspection Station Eureka, CA	Passed emissions inspection
12/27/1991		California Motor Vehicle Dept.	Title issued or updated
01/13/1993	19,626	California Inspection Station Eureka, CA	Passed emissions inspection
01/11/1995	31,596	California Inspection Station Eureka, CA	Passed emissions inspection
01/14/1997	40,296	California Inspection Station Eureka, CA	Passed emissions inspection
01/12/1999	44,470	Service Facility Eureka, CA	Vehicle serviced
01/12/1999		California Inspection Station Eureka, CA	Passed emissions inspection
01/11/2000		California Motor Vehicle Dept. Carmel by the Sea, CA	Title issued or updated
01/11/2001	51,474	Service Facility Eureka, CA	Vehicle serviced
01/11/2001		California Inspection Station Eureka, CA	Passed emissions inspection
01/14/2003	57,909	Service Facility Eureka, CA	Vehicle serviced
01/14/2003		California Inspection Station Eureka, CA	Passed emissions inspection
03/08/2004	60,910	Service Facility	Vehicle serviced
03/08/2004		Mercedes-Benz of Monterey Monterey, CA 831-375-2456 montereymercedes.com	Recommended maintenance performed 60,000 mile service performed Antifreeze/coolant flushed/changed Brake fluid flushed/changed Oil and filter changed Power steering fluid flushed/changed Rear brake pads replaced Wiper(s) replaced
04/16/2004	61,176	Service Facility	Battery replaced
04/16/2004		Mercedes-Benz of Monterey Monterey, CA 831-375-2456 montereymercedes.com	Battery replaced
08/03/2004	61,680	Service Facility	Engine checked
08/03/2004		Mercedes-Benz of Monterey Monterey, CA 831-375-2456 montereymercedes.com	Engine checked
12/08/2004	62,812	Service Facility	Doors checked Front brake pads replaced
12/08/2004		Mercedes-Benz of Monterey Monterey, CA 831-375-2456 montereymercedes.com	Doors checked Front brake pads replaced
01/19/2005	62,993	California Inspection Station	Failed emissions inspection <b>Designated GROSS POLLUTER</b>
01/21/2005		Vehicle Repair Center	Oxygen sensors repaired

			Vehicle serviced
01/21/2005	63,026	Service Facility	Engine checked Exhaust repaired Floor console replaced Oxygen sensor replaced Window switch replaced Emissions inspection performed
01/21/2005		Mercedes-Benz of Monterey Monterey, CA 831-375-2456 montereymercedes.com	Engine checked Oxygen sensor replaced Power window computer/module replaced Emissions inspection performed
01/21/2005		California Inspection Station	Passed emissions inspection
11/23/2005		Mercedes-Benz of Monterey Monterey, CA 831-375-2456 montereymercedes.com	A/C and heating system checked Oil and filter changed
12/05/2005		Mercedes-Benz of Monterey Monterey, CA 831-375-2456 montereymercedes.com	Vehicle serviced
06/15/2006		Mercedes-Benz of Monterey Monterey, CA 831-375-2456 montereymercedes.com	Vehicle serviced
01/12/2007	67,130	California Inspection Station	Passed emissions inspection
11/19/2007		Mercedes-Benz of Monterey Monterey, CA 831-375-2456 montereymercedes.com	Oil and filter changed
01/12/2009	68,649	California Inspection Station Carmel by the Sea, CA	Passed emissions inspection
01/10/2011	69,881	California Inspection Station Carmel by the Sea, CA	Passed emissions inspection
07/18/2011		California Motor Vehicle Dept. Carmel, CA	Registration updated when owner moved the vehicle to a new location
01/30/2013	71,989	California Inspection Station Seaside, CA	Passed emissions inspection
12/22/2014	74,051	C & C Repair Monterey, CA	Tire condition and pressure checked
01/22/2015	74,164	California Inspection Station Seaside, CA	Passed emissions inspection
02/16/2015	74,205	C & C Repair Monterey, CA	Tire condition and pressure checked
02/27/2015	74,257	C & C Repair Monterey, CA	Tire condition and pressure checked



Hmm, we haven't received any information on this car since February 2015. Before you buy, ask the seller for recent service or repair records.

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



Glossary

[View Full Glossary](#)

**Failed Emissions Inspection**

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

**Gross Polluter**

A Gross Polluter is a vehicle that fails an emissions inspection with below-standard scores. These vehicles can pollute as much as 18 times more than a vehicle that passes an emissions inspection. It is illegal to drive or sell a gross polluting vehicle in California, and it cannot be registered with the DMV. CARFAX recommends checking the latest Vehicle Inspection Report to confirm the proper repairs have been completed before purchasing.

**Title Issued**

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

**Follow Us:** [facebook.com/CARFAX](https://www.facebook.com/CARFAX) [@CarfaxReports](https://twitter.com/CarfaxReports) [CARFAX on Google+](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2017 CARFAX, Inc., a unit of IHS Inc. All rights reserved.  
Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.  
7/7/17 8:47:18 PM (EDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 1987 MERCEDES-BENZ 500 SERIES vehicle (VIN: WDBBA48DXHA070677), which is based on information supplied to CARFAX and available as of 7/7/17 at 8:47 PM (EDT).

\_\_\_\_\_  
Customer Signature

\_\_\_\_\_  
Date

\_\_\_\_\_  
Dealer Signature

\_\_\_\_\_  
Date