

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/11/17 at 3:47:12 PM (EDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Title History CARFAX guarantees the information in this section	Summary
Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem

CARFAX Additional History Not all accidents / issues are reported to CARFAX	Summary
Total Loss No total loss reported to CARFAX.	No Issues Reported
Structural Damage No structural damage reported to CARFAX.	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported
Odometer Check Potential odometer rollback indicated.	Potential Rollback
Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported
Manufacturer Recall Check with an authorized Porsche dealer for any open recalls.	No Recalls Reported



Glossary

Date:	Mileage:	Source:	Comments:
12/13/1991		California Motor Vehicle Dept.	Title issued or updated First owner reported
06/10/1992		California Motor Vehicle Dept.	Title issued or updated
10/12/1994	31,941	California Inspection Station Belmont, CA	Passed emissions inspection
03/08/1996	48,415	Inspection Co. California	Anti-theft device present at the time of inspection Vehicle inspected
11/18/1996	55,628	California Inspection Station Belmont, CA	Passed emissions inspection
12/18/1996		California Motor Vehicle Dept.	Title issued or updated New owner reported Loan or lien reported
10/12/1998	74,358	Service Facility Belmont, CA	Vehicle serviced
10/12/1998		California Inspection Station Belmont, CA	Passed emissions inspection
12/02/1999		California Motor Vehicle Dept. Portola Valley, CA	Title issued or updated
09/22/2000	96,775	Service Facility Belmont, CA	Vehicle serviced
09/22/2000		California Inspection Station Belmont, CA	Passed emissions inspection
10/11/2002	117,731	Service Facility Belmont, CA	Vehicle serviced
10/11/2002	117,759	Service Facility Belmont, CA	Vehicle serviced
10/11/2002		California Inspection Station Belmont, CA	Passed emissions inspection
01/01/2003		California Motor Vehicle Dept. Redwood City, CA	Title issued or updated
02/03/2003		California Motor Vehicle Dept. Redwood City, CA	Registration updated when owner moved the vehicle to a new location
11/10/2004	140,481	California Inspection Station Redwood City, CA	Passed emissions inspection
10/30/2006	159,474	California Inspection Station Redwood City, CA	Passed emissions inspection
12/18/2006	160,337	Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Maintenance inspection completed Antifreeze/coolant checked Battery serviced Body lubricated Brake calipers cleaned/serviced Brake pads replaced Brake system bled Drivability/performance checked Maintenance reminder reset Oil and filter changed Rear brake pads replaced Rear brakes serviced/adjusted Steering/suspension lubricated

	, , , F	CARFAX Vehicle History Report for this 1991 PORSCHE 911 CARRERA2/4: WP0CB2966MS460820				
		Tire condition and pressure checked Wheel bearings repacked				
170,383	Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Maintenance inspection completed Antifreeze/coolant checked Battery serviced Body lubricated Drivability/performance checked Maintenance reminder reset Oil and filter changed Steering/suspension lubricated Tire condition and pressure checked				
	Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	A/C refrigerant recharged Left front window switch replaced				
172,517	Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Vehicle serviced				
175,014	California Inspection Station	Passed emissions inspection				
	Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Maintenance inspection completed Antifreeze/coolant checked Battery serviced Body lubricated Drivability/performance checked Maintenance reminder reset Oil and filter changed Steering/suspension lubricated Tire condition and pressure checked Emissions inspection performed				
180,857	Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Maintenance inspection completed Antifreeze/coolant checked Battery serviced Body lubricated Drivability/performance checked Maintenance reminder reset Oil and filter changed Steering/suspension lubricated Tire condition and pressure checked				
46,858	Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Maintenance inspection completed A/C system checked Antifreeze/coolant checked Battery serviced Body lubricated Drivability/performance checked Maintenance reminder reset Oil and filter changed Steering/suspension lubricated Tire condition and pressure checked Tires rotated				
	172,517 175,014 180,857	Portola Valley, CA 650-851-7442 pvgarage.com Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com 172,517 Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com 175,014 California Inspection Station Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com 180,857 Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com 46,858 Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Wheel bearings repacked Wheel bearings repacked Portola Valley, CA 650-851-7442 Pygarage.com Maintenance inspection completed Antifreeze/coolant checked Battery serviced Body lubricated Drivability/performance checked Maintenance reminder reset Oil and filter changed Steering/suspension lubricated Tire condition and pressure checked Portola Valley, CA 650-851-7442 Pygarage.com Vehicle serviced Portola Valley Garage Portola Valley, CA 650-851-7442 Pygarage.com Maintenance inspection completed Antifreeze/coolant checked Battery serviced Body lubricated Drivability/performance checked Maintenance reminder reset Oil and filter changed Steering/suspension lubricated Tire condition and pressure checked Battery serviced Body lubricated Drivability/performance checked Portola Valley, CA 650-851-7442 Pygarage.com Maintenance reminder reset Oil and filter changed Steering/suspension lubricated Drivability/performance checked Battery serviced Body lubricated Drivability/performance checked Battery serviced Body lubricated Drivability/performance checked Portola Valley, CA 650-851-7442 Pygarage.com Maintenance reminder reset Oil and filter changed Steering/suspension lubricated Drivability/performance checked Battery serviced Body lubricated Drivability/performance checked Drivability/performance checked Drivability/performance checked Drivability/performance checked Battery serviced Body lubricated Drivability/performance checked Driv			



verify the mileage with the seller. I know I would.

46,898	Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Vehicle serviced	
	California Inspection Station	Failed emissions inspection	
	California Inspection Station Redwood City, CA	Failed emissions inspection Passed emissions inspection	
	46,898	Portola Valley, CA 650-851-7442 pvgarage.com California Inspection Station California Inspection Station	Portola Valley, CA 650-851-7442 pvgarage.com California Failed emissions inspection Inspection Station California Failed emissions inspection Inspection Station Passed emissions inspection

1/2017	CF	Kraa vehicle history keport i	or this 1991 PORSCHE 911 CARRERA2/4: WP0CB2966MS460820
11/03/2010		Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Vehicle serviced
03/14/2011		Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Maintenance inspection completed Antifreeze/coolant checked Battery serviced Body lubricated Drivability/performance checked Maintenance reminder reset Oil and filter changed Steering/suspension lubricated Tire condition and pressure checked
12/23/2011	79,896	Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Maintenance inspection completed Antifreeze/coolant checked Battery serviced Body lubricated Brake system bled Drivability/performance checked Front brake pads replaced Fuel pump replaced Maintenance reminder reset Oil and filter changed Starter replaced Steering/suspension lubricated Tire condition and pressure checked Wheel bearings repacked
01/24/2012	79,919	Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Engine valves adjusted Spark plug(s) replaced Switch replaced/repaired
04/24/2012		Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Vehicle serviced
07/20/2012		Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Vehicle serviced
09/24/2012	82,460	California Inspection Station Redwood City, CA	Passed emissions inspection
09/25/2012		Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Alternator replaced
03/12/2013		California Motor Vehicle Dept. Portola Valley, CA	Registration updated when owner moved the vehicle to a new location
03/21/2014	84,725	Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Maintenance inspection completed A/C refrigerant recharged Antifreeze/coolant checked Battery serviced Body lubricated Drivability/performance checked Maintenance reminder reset Oil and filter changed Steering/suspension lubricated Tire condition and pressure checked
12/05/2014	86,680	Portola Valley Garage Portola Valley, CA 650-851-7442 pvgarage.com	Maintenance inspection completed Tire condition and pressure checked Emissions inspection performed
12/05/2014		California Inspection Station Portola Valley, CA	Passed emissions inspection
05/11/2015	87,761	Service Facility	Computer(s) checked Drivability/performance checked

09/02/2016	88,910	Service Facility	Maintenance inspection completed Antifreeze/coolant checked Battery serviced Drivability/performance checked Maintenance reminder reset Oil and filter changed Tire condition and pressure checked	
09/22/2016		California Motor Vehicle Dept. Portola Valley, CA	Title issued or updated Duplicate title issued	
10/05/2016	88,950	Service Facility	Emissions inspection performed	
10/05/2016		California Inspection Station Portola Valley, CA	Passed emissions inspection	
06/07/2017		Service Facility	Exterior lights checked Rear brakes replaced	

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



View Full Glossary

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Odometer Rollback

If a more recent odometer reading is less than an older reading, then the odometer may have been tampered with and "rolled back." CARFAX analyzes the mileage history and the sources of this information to indicate a potential odometer rollback.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:





CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2017 CARFAX, Inc., a unit of IHS Inc. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838. 7/11/17 3:47:12 PM (EDT)

I have reviewed and received a copy of the vehicle (VIN: WP0CB2966MS460820), which 7/11/17 at 3:47 PM (EDT).			
Customer Signature	Date	Dealer Signature	Date